

FIG. 1





FIG. 2



3/7

FIG. 3

PC MATERIAL  
 $B_m=0.2T$   
 $f=8Hz$




FIG. 4

PC MATERIAL  
 $B_m=0.2T$   
 $f=8Hz$





FIG. 5



5/7

FIG. 6

PC MATERIAL  
 $B_m = 0.65T$   
 $f = 50Hz$





FIG. 7

PC MATERIAL  
 $B_m = 0.65T$   
 $f = 50Hz$



6/7

FIG. 8

PB MATERIAL  
 $B_m = 0.9T$   
 $f = 50Hz$





FIG. 9

PD MATERIAL  
 $B_m = 0.9T$   
 $f = 50Hz$



P5878a, Serial No.: 10/002,033  
Customer No. 20178

7/7

FIG.10

PC MATERIAL  
 $B_m = 0.65T$   
 $f = 100Hz$

